

RECEIVED

AUG 02 2021

**ATTACHMENT B
72 HOUR FOLLOW-UP NOTIFICATION REPORT FORM
CONTRA COSTA HEALTH SERVICES**

Contra Costa Health
Hazardous Materials

For CCHS Use Only:

Received By: MO
Date Received: 8/2/21
Incident Number: 21072902
Copied To: _____
Event Classification Level: 1

INSTRUCTIONS:A hardcopy and an electronic copy of this report is to be submitted for all Level 2 and 3 incidents or when requested by CCHS. See Attachment B-1 for suggestions regarding the type of information to be included in the report. Attach additional sheets as necessary. Forward the completed form to:

ATTENTION: Randall L. Sawyer
Hazardous Materials Programs Director
Contra Costa Health Services
4585 Pacheco Boulevard, Suite 100
Martinez, CA 94553

INCIDENT DATE: 7/29/2021
INCIDENT TIME: 2:34 PM
FACILITY: Dwellely Family Farms

PERSON TO CONTACT FOR ADDITIONAL INFORMATION

Patrick Johnston Phone number (925) 270-8526 / (925) 634-8101

I. SUMMARY OF EVENT:

Ammonia odor and plume detected from Ice Generator. Notified all facility employees to evacuate. All employees accounted for at 2:38 pm; no injuries reported.

II. AGENCIES NOTIFIED, INCLUDING TIME OF NOTIFICATION:

2:34 pm (7 min.) - 911 operator; Transferred to Sheriff, Oakley Police, then Contra Costa County Fire. 2:51 pm - Contra Costa County Health Services Female. handed phone off to Captain Robert Ruddick to advise hazmat team of the situation. 3:37pm spoke with Michael Dossev. Hazmat team was on site at this time. 5:24 pm - Office of Emeraencv

III. AGENCIES RESPONDING, INCLUDING CONTACT NAMES AND PHONE NUMBERS:

Fire Department arrived approx. 10 min. after 911 call. Captain Robert Ruddick point of contact until Battalion Chief(forgot name) arrived on scene. Contra Costa Hazmat team Matt Kaufman, then arrived on scene approx 20mins later, gathered first responders together to assign responsibilities. Devra Lewis Contra Costa Hazmat team

IV. EMERGENCY RESPONSE ACTIONS:

Evacuated employees to protect life and health. Fire Department isolated area. Zero ppm detected at road/fruit stand. Hazmat team Devra suited up and shut of compressor at 3:35 pm. Hazmat determined most had already released. Waited for refrigeration contractor, then released facility.

V. IDENTITY OF MATERIAL RELEASED AND ESTIMATED OR KNOWN QUANTITIES:

Anhydrous ammonia release. Approximately 2,000 lbs.

72-HOUR REPORT, PAGE 2

INCIDENT DATE: 7/29/2021
FACILITY: Dwelley Family Farms

VI. **METEOROLOGICAL CONDITIONS AT TIME OF EVENT** including wind speed, direction, and temperature:
10-15 MPH wind from the NW to SE. 99 degrees.

VII. **DESCRIPTION OF INJURIES:**
No injuries.

VIII. **COMMUNITY IMPACT** including number of off-site complaints, air sampling data during event, etc.:
No complaints. Zero ppm detected at property line.

IX. **INCIDENT INVESTIGATION RESULTS**

Is the investigation of the incident complete at this time? _____ Yes _____ No
If the answer is no, submit a 30 day final or interim report.

If the answer is yes, complete the following:

X. **SUMMARIZE INVESTIGATION RESULTS BELOW OR ATTACH COPY OF REPORT:**

Full investigation pending. Initial findings include failure of a stainless steel hose compression fitting to bank 3 ice plate. Have checked/tightened other hoses. Have pressure tested svstem. No other leaks detected.

XI. **SUMMARIZE PREVENTATIVE MEASURES TO BE TAKEN TO PREVENT RECURRENCE INCLUDING MILESTONE AND COMPLETION DATES FOR IMPLEMENTATION:**