


WILLIAM B. WALKER, M.D.  
HEALTH SERVICES DIRECTOR

RANDALL L. SAWYER  
CHIEF ENVIRONMENTAL HEALTH AND  
HAZARDOUS MATERIALS OFFICER

CONTRA COSTA  
HEALTH SERVICES  
HAZARDOUS MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100  
Martinez, California  
94553-2233  
Phone (925) 335-3200  
Fax (925) 646-2073



# CONTRA COSTA HEALTH SERVICES

## COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One):  C  I  N

CASE NUMBER: 17-05-26 - 01

Received Date: 05/26/17 Received Time: 3:14 PM Received By: AM Lead: SD

Incident Date: 5/26/17 Incident Time: 3:14 PM Assigned to: Assigned Date:

### COMPLAINANT / REPORTING PARTY:

Name: BC DOMINIC CIOTOLA  RP is from Facility  Anonymous

Organization: CON FIRE

Primary Phone Number: (925)383-5043 Secondary Phone Number:

Email:

Address:

City: State: Zip Code:

### FACILITY / LOCATION OF INCIDENT:

Name: CUPA Facility I.D.:

Phone Number:

Address: Solano Way at Marsh Dr Unit:

City: Concord State: CA Zip Code: 94520

Location Description: intersection of Solano Way and Marsh Drive

INITIAL INCIDENT DESCRIPTION: Small plane crash, fuel leaking

### INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level):  N/A  0  1  2  3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input type="checkbox"/> Storm Drain/Creek
<input checked="" type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring		<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Other:

Time Enroute to Scene: 3:27 PM Time Arrived On Scene: 3:41 PM Time Departed From Scene: 7:12 PM

### REFERRED TO OTHER AGENCY:

### DTSC STATE FUNDING (if applicable):

CLU/ERER Number:

### STORMWATER STATUS (if applicable):

Actual Discharge  Potential Discharge



**AGENCIES ON SCENE OR NOTIFIED:**

<b>Agency Type</b>	<b>Agency</b>	<b>O/N</b>	<b>Contact Person</b>	<b>Phone Number</b>	<b>Case Number</b>
Fire Department	Con Fire	O	Dominic Ciotola	925-383-5043	
Law Enforcement	Concord Police Dept	O	Todd Stroud	925-671-3311	
Air District					
State OES					
	Federal Aviation Administration (FAA)	O	Matt DeSeelhorst	510-748-0122	
	Contra Costa County (Buchanan and Byron Airports)	O	Keith Freitas	925-382-1715	
	Contra Costa County (Buchanan and Byron Airports)	O	Bikramjit Bhullar	844-359-8687	

**REPORT:**

On May 26, 2017 at 3:14 PM, Contra Costa Health Services Hazardous Materials Programs (CCHS HMP) Incident Response Team received notification from Con Fire that a small aircraft had crashed at the intersection of Marsh Drive and Solano Way in Concord, CA, just outside the Buchanan Airport. Con Fire incident commander reported that approximately 15 gallons of fuel had leaked out of the plane onto the ground and that absorbant had been placed to prevent fuel from entering the storm drain. A slow leak from the wing fuel tank was ongoing.

CCHS HMP Hazardous Materials Specialists M. Duazo, K. Abramians, L. Friedman, and S. Dwight responded in HM1 and HM3, arriving on scene at 3:41 PM. CCHS HMP personnel performed air monitoring in the vicinity of the crash using a PID and 4 gas meter and confirmed that no readings above background were detected in areas where personnel were staged. Response operations could not commence until the Federal Aviation Administration (FAA), in conjunction with the National Transportation Safety Board, evaluated the scene. After clearance from the FAA, two CCHS HMP personnel (L. Friedman and K. Abramians) donned level C respiratory protection and turnouts and removed and containerized the aviation gas from the two wing tanks of the plan. Two CCHS HMP personnel (M. Duazo and S. Dwight) performed additional air monitoring and back up entry roles. Contra Costa County Buchanan Airport personnel manned a hose line as an emergency precaution. CCHS HMP personnel then mitigated the aviation gas on the ground using additional absorbant and containerized the waste. One 30 gallon drum of waste aviation gas, one 5 gallon container of absorbant contaminated with aviation gas, and one 5 gallon container of oily debris were transported to the CCHS HMP hazardous waste storage area for disposal.

HM1 and HM3 departed the scene at 7:12 PM.

**Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan**

Report Prepared by: S. Dwight