


Assessment Diagram
 Contra Costa County LL-2
 Zone 48
 Oakgate Drive – Danville Area



- LEGEND**
- Frontage/Median Landscaping
 - Parks
 - Open Space
 - Trails
 - Indicates Maintenance Area from Part A in Engineer's Report

Landscaping, irrigation, and related improvements within the public right-of-way along:

1. Oakgate Drive; and
2. The north side frontage of Camino Tassajara from 600' west of Oak Gate Drive to Hansen Lane

