



COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

CASE NUMBER: 190423 — 01

Received Date: 04/23/19 Received Time: 8:00am Received By: HW Lead: ED

Incident Date: 04/23/19 Incident Time: Assigned to: Assigned Date:

COMPLAINANT / REPORTING PARTY:

Name: RICH RP is from Facility Anonymous

Organization: PUBLIC WORKS DEPARTMENT

Primary Phone Number: 925-260-5081 Secondary Phone Number:

Email:

Address:

City: State: Zip Code:

FACILITY / LOCATION OF INCIDENT:

Name: CUPA Facility I.D.:

Phone Number:

Address: SHELL AVE. AND PACHECO BLVD. Unit:

City: MARTINEZ State: CA Zip Code: 94553

Location Description: Roadway along Shell Ave. north of Pacheco Blvd.

INITIAL INCIDENT DESCRIPTION:

TRUCK LEAKED HYDRAULIC FLUID AT SHELL AVE & PACHECO. MAIN SPILL IS SEVERAL HUNDRED FEET LONG. TRUCK IS PARKED AT HOWE RD AND PACHECO BLVD.

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input type="checkbox"/> Storm Drain/Creek
<input type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring	<input type="checkbox"/> > 5,000 lbs.	<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input checked="" type="checkbox"/> Other: ROADWAY

Time Enroute to Scene: 0815 Time Arrived On Scene: 0820 Time Departed From Scene: 0915

REFERRED TO OTHER AGENCY:



DTSC STATE FUNDING (if applicable): CLU/ERER Number:	STORMWATER STATUS (if applicable): <input type="checkbox"/> Actual Discharge <input checked="" type="checkbox"/> Potential Discharge
--	--

AGENCIES ON SCENE OR NOTIFIED:

<u>Agency Type</u>	<u>Agency</u>	<u>O/N</u>	<u>Contact Person</u>	<u>Phone Number</u>	<u>Case Number</u>
Fire Department	CON FIRE	O			
Law Enforcement	HIGHWAY PATROL	O			
Air District					
State OES					
LOCAL	CC PUBLIC WORKS	O	RICH	925-260-5081	

REPORT:

DAVEY TREE EXPERT COMPANY TREE TRIMMING TRUCK RELEASED HYDRAULIC OIL INTO ROADWAY ALONG SHELL AVE. NORTH OF PACHECO. RELEASE EXTENDED APPROXIMATELY 200 FEET ALONG ROADWAY. CCHSHM ALONG WITH PUBLIC WORKS AND CON FIRE USED ABSORBENT TO CLEAN UP RELEASE IN THE ROADWAY. NO FUTHER ACTION NEEDED.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan
 Report Prepared by: ED